## **EAST Search History**

| Ref<br># | Hits | Search Query                              | DBs                          | Default<br>Operator | Plurals | Time Stamp       |
|----------|------|---|------------------------------|---------------------|---------|------------------|
| L1       | 71   | (280/86.758).CCLS.                        | US-PGPUB;<br>USPAT;<br>USOCR | OR                  | OFF     | 2006/06/28 09:53 |
| L2       | 122  | (280/86.757).CCLS.                        | US-PGPUB;<br>USPAT;<br>USOCR | OR                  | OFF     | 2006/06/28 09:53 |
| L3       | 189  | (280/86.75).CCLS.                         | US-PGPUB;<br>USPAT;<br>USOCR | OR                  | OFF     | 2006/06/28 09:53 |
| L4       | 192  | (280/86.751).CCLS.                        | US-PGPUB;<br>USPAT;<br>USOCR | OR                  | OFF     | 2006/06/28 09:53 |
| L5       | 94   | (280/86.753).CCLS.                        | US-PGPUB;<br>USPAT;<br>USOCR | OR                  | OFF     | 2006/06/28 09:53 |
| L6       | 69   | (280/86.754).CCLS.                        | US-PGPUB;<br>USPAT;<br>USOCR | OR                  | OFF     | 2006/06/28 09:53 |
| L7       | 110  | (280/86.756).CCLS.                        | US-PGPUB;<br>USPAT;<br>USOCR | OR                  | OFF     | 2006/06/28 09:53 |
| L8       | 737  | L1 L2 L3 L4 L5 L6 L7                      | US-PGPUB;<br>USPAT;<br>USOCR | OR                  | ON      | 2006/06/28 10:08 |
| L9       | 14   | (cam projections plate washer bolt). clm. | US-PGPUB;<br>USPAT;<br>USOCR | AND                 | ON      | 2006/06/28 10:09 |

6/28/2006 10:10:49 AM 6/28/2006 10:10:49 AM Page 1
C:\Documents and Settings\dbrown3\My Documents\EAST\Workspaces\10740202 Toe link adjuster w cam sleeve and plates and washer